

PL12 – Addendum Information
Submitted by Epic Energy on behalf of Pipeline Owner Heathgate

1) Typing Error

PIRSA advised that a typing error existed in section 14. This section refers to the proposed operational activities for 2006 licence year. It should be 2007.

Epic/Heathgate Response:

This has been noted and we apologize for any inconvenience.

2) Section 5 – Incident Reporting

PIRSA advised that this section does not refer to the incidents mentioned in “Appendix A – Statement of Environmental Incidents”

Epic/Heathgate Response:

This was an oversight and we apologize for any inconvenience. Section 5 of the report should read as per below.

5 INCIDENT REPORTING

There were two incidents to report on the Beverley pipeline during 2006.

- An unauthorized encroachment on the pipeline easement
- A solar panel array failure spilling a quantity of battery acid

3) Section 12

PIRSA advised that in section 12 the following items should be noted:

- *Quarterly Incident reports*

Epic Response:

This has been noted.