Office of the Technical Regulator

Safety Alert: open flued gas space heaters

Fireplace Products Australia and Glen Dimplex Australia

February 2019

The Office of the Technical Regulator has placed a Safety Alert on four open-flued gas space heaters.

The safety alert applies to the following models:

- Regency i31
 - Supplied by Fireplace Products Australia Pty. Ltd
- Regency F38 and FG38
 - Supplied by Fireplace Products Australia Pty Ltd. The F38/FG38 was branded and supplied by **Masport** prior to 2006 (excludes LP units)
- Nectre 2000 manufactured from 2007
 Supplied by Glen Dimplex Australia Pty. Ltd
- Real Flame Pyrotech manufactured from 2012 Supplied by Glen Dimplex Australia Pty. Ltd.

What do I need to do?

If you have one of these open flued gas space heaters, do not use it until after you have contacted the relevant supplier and had it inspected. The two suppliers are:

Fireplace Products Australia

Email: safety@regency-fire.com.au

Phone: 1800 860 660

Glen Dimplex Australia

Email: productservice@realflame.com.au

Phone: 1300 014 389

Not all of these model heaters are a safety concern. It depends on the date they were made or supplied. Fireplace Products Australia or Glen Dimplex Australia will tell you if your heater needs to be checked.

What can I expect from the supplier?

After registering your details with the relevant supplier, they will send out a qualified gasfitter to inspect your heater.

There is a technical fix available that will be carried out at the supplier's expense.

However, if other faults are detected (e.g. installation faults), you (or the person who is the property owner) may be responsible for the cost of these repairs. The gasfitter will discuss options with you.

Am I in danger?

The circumstances that can lead to carbon monoxide entering a building are complex. Among the contributing factors are well-sealed energy efficient houses and the operation of exhaust fans and kitchen rangehoods.

At a basic level, if the house is well sealed (with little ventilation) and the heater is running at the same time as an exhaust fan (a kitchen range hood or a bathroom fan), carbon monoxide can be drawn into living areas.

If you have one of these heaters, do not use it until it can be tested by a qualified gasfitter.

Continued...



Why has it taken so long to identify these faults?

As a result of a fatality in Victoria from carbon monoxide poisoning connected to a Vulcan Heritage open flued gas space heater, and a subsequent Coronial Inquest, Energy Safe Victoria required certification bodies to test all open flued gas space heaters that were certified for sale at the time. This testing revealed a range of non-compliances with seven models of open flued heater, but only four of those presented safety concerns and are now subject to a Safety Alert.

Contact the Office of the Technical Regulator for more information

Online sa.gov.au/otr Email otr@sa.gov.au Phone 1300 760 311

