

Howe, Mark (DMITRE)

From: Frederick Glanville [REDACTED]
Sent: Friday, 8 November 2013 2:06 PM
To: DMITRE:MiningRegRehab
Subject: rex minerals mine lease dear mark

i am concerned about rex minerals mine vibration from 2700 ten ton explosions may result in leaking septic tank connection pipes may be cracked and can leak and run into ground and sea no one will know some septic tanks are connected with earthenware pipes and will not take vibration who will monitor this you have to dig up all septic tanks to be checked

File No: T2951-V02
Doc No: A1806405