

# **PUBLIC WARNING: DANGERS OF ARTISTIC WOOD BURNING USING ELECTRICITY**

## ***Electricity Act 1996 Section 62A***

The practice of using electricity to burn patterns into wood is extremely dangerous and is suspected to have resulted in a recent fatality to a member of the public. It appears that the deceased was attempting to apply a high voltage to a timber table top.

High-voltage work should only be performed by licensed and qualified professionals. Removing or modifying electrical components from appliances or equipment is also extremely dangerous.

For further information please contact the Office of the Technical Regulator on (08) 8226 5518

**R Faunt**

**Technical Regulator**

---



**Government of  
South Australia**

PN2615

T21 (92x63mm)

Barossa Light Herald, Flinders News  
Wednesday April 11 2018

The Islander, Naracoorte Herald, Port Lincoln Times,  
Victor Harbor Times, Stock Journal  
Thursday April 12 2018

Murray Pioneer  
Friday April 13 2018

# **PUBLIC WARNING: DANGERS OF ARTISTIC WOOD BURNING USING ELECTRICITY**

## ***Electricity Act 1996 Section 62A***

The practice of using electricity to burn patterns into wood is extremely dangerous and is suspected to have resulted in a recent fatality to a member of the public. It appears that the deceased was attempting to apply a high voltage to a timber table top.

High-voltage work should only be performed by licensed and qualified professionals. Removing or modifying electrical components from appliances or equipment is also extremely dangerous.

For further information please contact the Office of the Technical Regulator on (08) 8226 5518

**R Faunt**

**Technical Regulator**

---



**Government of  
South Australia**

PN2615

9x2 (72mm)

Mt Gambier Border Watch

Wednesday April 11 2018

Weekender Herald, Coober Pedy Times

Thursday April 12 2018

# **PUBLIC WARNING: DANGERS OF ARTISTIC WOOD BURNING USING ELECTRICITY**

## ***Electricity Act 1996 Section 62A***

The practice of using electricity to burn patterns into wood is extremely dangerous and is suspected to have resulted in a recent fatality to a member of the public. It appears that the deceased was attempting to apply a high voltage to a timber table top.

High-voltage work should only be performed by licensed and qualified professionals. Removing or modifying electrical components from appliances or equipment is also extremely dangerous.

For further information please contact the Office of the Technical Regulator on (08) 8226 5518

**R Faunt**

**Technical Regulator**

---



**Government of  
South Australia**

PN2615

M3x2 (92x85mm)

Adelaide Advertiser

Saturday April 14 2018