

**HONEYMOON URANIUM PROJECT - SPILL INCIDENT SUMMARY AS REPORTED BY SOUTHERN CROSS RESOURCES**

*(Includes incidents where reporting is not required under the spill notification criteria)*

<b>Date of Spill/s</b>	<b>Date Reported</b>	<b>Spill Notification Criteria*</b>	<b>Quantity</b>	<b>Description</b>	<b>Comments</b>
19/02/1999	21/05/1999	4	1000L	Barren solution spilled in plant area.	Reported as per attached Spill Notification Criteria.
19/02/1999	21/05/1999	4	200L	Injection fluid spilled in wellfield area due to faulty venting valve on injection well.	Reported as per attached Spill Notification Criteria.
7/05/1999	21/05/1999	2	360L	Injection fluid from well-head. Extremely low activity liquid (17ppm U).	Reported as per attached Spill Notification Criteria.
3/10/1999	6/10/1999	3	9600L	Spill of process fluid in bunded concrete lined area due to valve failure and pipe rupture.	Material was recovered from the bunded area. All valves were checked and pipes replaced where necessary. Delayed reporting explained by SXR.
4/07/2000	4/07/2000	3	2000L	Spill of injection fluid in wellfield with slightly elevated uranium (30mg/L U <sub>3</sub> O <sub>8</sub> ) due to cracked PVC fitting.	Reported as per attached Spill Notification Criteria.
22/05/2001	22/05/2001	3	30 000L	Spill of Basal aquifer groundwater (~1ppm U) about 3km east of the wellfield, due to split layflat pipe during hydrological pump testing.	Reported as per attached Spill Notification Criteria.

<b>SPILL NOTIFICATION CRITERIA*</b>			
<b>FOR ISL URANIUM MINING OPERATIONS</b>			
<b>CLASS</b>	<b>DEFINITION</b>	<b>QUANTITY (litres)</b>	<b>REPORTING REQUIRED</b>
1	Spills of raw Groundwater	>2,000, <10,000	Verbally at Quarterly ISL meeting
		>10,000	Written report to Chief Inspector of Mines within 24 hours
2	Spill of leach liquids in well-field outside bunded areas	>200, <2000	Verbal report to regulators at Quarterly Meeting
		>2000	Written report to Chief Inspector of Mines within 24 hours
3	Spill of leach liquids within plant bunds	bund volume exceeded or uncontrolled spill >2000 L	Written report to Chief Inspector of Mines within 24 hours
4	Reported by company for information only		None